ED ENGINEERING CONSULTANTS, INC

Building Condition Surveys
Contract Administration
Corrosion Control Design
Structural Inspection & Design
Project Planning & Management

FIELD OVSERVATION REPORT PERMIT # BLDC-000287-2020

		Report No. 57	Page 1 of 1
Project:	Southpoint Condominium	Inspection For:	Restoration Project
Day/Date:	Thursday, November 19, 2020	Job No.	19-1086
Location:	4453 S. Atlantic Ave, Ponce Inlet	Engineer:	Timothy J. Snook, P.E.
Contractor:	ACE Enterprises, LLC	Project Foreman:	Wes Swaim
Subcontractor:	N/A	Inspector:	Timothy J. Snook, P.E.
Weather:	74 Degrees @ 7:50 A.M. Overcast	Windy 20% Chance of Rain	
Workforce Total:	8		
Activities:	Coating removal, concrete demo, pressure wash, rust spot repair		


Observation Report:

Deck coating removal continues on the 06 balcony stack. It appears that some of the previous concrete repairs were cast at the elevation of the deck coating instead of at the elevation of the concrete deck. These repairs will need to be ground down to match the elevation of the concrete deck to properly deck coat the balconies.

Concrete demolition continues on the North half of the garage.

Pressure washing and preparing for paint application is in-progress on the 8 and 9 balcony stacks.

Repairing the rust spots on the soffit in the garage is in-progress. The existing heads of the fasteners are corroding causing the rust spots. The Contractor is grinding the existing fastener head and installing a new stainless-steel screw next to the existing. A small area of the soffit will be removed to verify that the new fasteners are attaching into the existing framing.



4240 South Ridgewood Avenue, Suite 4, Port Orange, FL 32127 • (386) 256-7684 • office@unitedengineeringconsultants.com Certificate of Authorization No. 6607