



UNITED ENGINEERING CONSULTANTS, INC.

- Building Condition Surveys
- Contract Administration
- Corrosion Control Design
- Structural Inspection & Design
- Project Planning & Management

FIELD OVSERVATION REPORT PERMIT # BLDC-000287-2020

		Report No. 1	Page 1 of 1
Project:	Southpoint Condominium	Inspection For:	Restoration Project
Day/Date:	Monday, May 4, 2020	Job No.	19-1086
Location:	4453 S. Atlantic Ave, Ponce Inlet	Engineer:	Timothy J. Snook, P.E.
Contractor:	ACE Enterprises, LLC	Project Foreman:	Wes Swaim
Subcontractor:	GAR Water Blasting (4)	Inspector:	Timothy J. Snook, P.E.
Weather:	74 Degrees @ 8:45 A.M. Sunny Light Breeze 0% Chance of Rain		
Workforce Total:	8		
Activities:	Mobilizing, strip parking deck coating, sound bottom side of parking deck		

Observation Report:


Project mobilization began today. A dumpster was delivered to the site and placed on the West side of the parking lot. Construction of swing stages is in-progress (See Photo 1).

The water blasting subcontractor mobilized on-site today and began stripping the topside of the parking deck (See Photo 2).

The Engineer was on-site to sound and mark concrete damage on the bottom side of the parking deck (bottom of slabs, beams and columns). Once the topside of the parking deck is stripped to the substrate, the Engineer will sound and mark damage on the topside of the deck. Demolition will begin after mobilization is complete.

UNITED ENGINEERING CONSULTANTS

Timothy J. Snook, P.E.
Florida License No. 83208



This item has been electronically signed and sealed by Timothy J. Snook using a Digital Signature and date. Printed Copies of this Document are not considered signed and sealed and the SHA authentication code must be verified on any electronic copies.



Picture 1: In-progress mobilization



Picture 2: In-progress stripping of coating on topside of parking deck